

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27

FC-R-2017-38
CUMBERLAND FIRE DISTRICT
Resolution

RESOLUTION: Authorizing the Finance Director to pay Ralco Equipment Co., Inc. an amount not to exceed \$5,181.10.


WHEREAS: Ralco Equipment Co., Inc. has made repairs to Engine 4.

WHEREAS: All repairs have been made with the approval of the Chief.

NOW, THEREFORE, BE IT RESOLVED BY THE CUMBERLAND FIRE DISTRICT AS FOLLOWS:

RESOLVED: The Finance Director is authorized to pay Ralco Equipment Co., Inc. an amount not to exceed \$5,181.10.

Voted on this 18th day of December, 2017



Cynthia Ouellette, Chairperson

PASSED:

YAY: 5 NAY: 0

Ralco Equipment Company, Inc
 51 Ralco Way/PO Box 35
 Cumberland, Rhode Island 02864-0035
 Phone: 401-726-3095 Fax: 401-726-6950
 We do the job once and we do it right!

9467
 Org. Est. # 016148
 RI Inspect Station 155C
 ralcotruck45@gmail.com

INVOICE

Print Date : 11/27/2017

Cumberland Fire Department - Chief Finlay
 3502 Mendon Road
 Cumberland, RI 02864
 Office 401-658-0544 --- Cellular 401-474-0314 Fin
 Cust ID : 934

2004 Pierce - Enforcer Fire Engine
 Cummins ISL, Disc Front, Drum rear
 Lic # : 1185 - RI Odometer In : 53,439
 Unit # : E4 Odometer Out :
 VIN # : 4P1CT02AX 4A003781

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Brake Clean C32	2.00	6.32	12.64	Remove and replace steer axle disc brake pads, air caliper.	0.00
Roloc Disc 01406	4.00	11.73	46.92	Jack up unit and support. Remove wheels and tires. Remove air caliper adjuster and back off brake pads. Remove worn pads. Clean and dress rotors on unit. Compress caliper and disassemble and clean slides. Install new OEM brake pads set. Lubricate all areas. Install new hardware retainer kits. Reinstall wheels and tires and verify brake operation. Adjust as needed.	
Surf Cond Disc 7485	4.00	6.97	27.88		
Power Lube 05006	1.00	7.53	7.53	Perform major brake job on unit, drive axle. ADD: Replace brake drums.	0.00
Surf Cond Disc Alum 07513	3.00	8.81	26.43	ADD: Upgrade brake chambers to 36 36 long throw heavy duty units.	
Brake Hdw Kit Air Caliper H9257	2.00	29.67	59.34	Jack up unit. Remove all wheels and tires. Back off brakes and remove drums. Remove brake shoes and hardware. Clean and inspect spider, s-cam shafts, seals, and brake chambers. Clean out all ABS sensors and adjust if equipped. Install new sets of premium brake shoes and linings. Install new spring roller hardware kits and lubricate pivot points. Install drums and secure. Install wheels and tires. Check and top off rear end, clean vent.	
Severe Duty Brake Pad Kit K109249	1.00	453.79	453.79	Adjust brakes and lubricate system. Remove from stands and test operation. ADD: Replace brake drums during repairs.	
Pad Attachment Kit H21193CM	2.00	37.52	75.04	ADD: Contact customer and recommend replacement of 30/30 standard duty brake chambers to heavier long throw 36/36 chambers as should be equipped on this unit. Customer approved repairs. Disconnect air lines and remove clevis pins and retainers. Remove hardware. Remove brake chambers. Cut to length new 36/36 chambers and install new yokes and jam nuts. Install on truck and secure with new hardware. Transfer and/or replace air fittings as needed. Connect and seal air liens to each chamber.	
Syn Slide Lube BK4	4.00	6.69	26.76	Install new clevis pin kits and lock pins. Adjust brakes and verify operation and adjustment.	
Sandpaper 02175	6.00	2.29	13.74	Labor Charge for above repairs.	1,945.38
Anti Seize NSBT-2	1.50	4.80	7.20	Two men used to get repairs done as efficiently as possible with a 24 hour turn around. Road test unit once repairs complete and verify brake operation, temp, and related.	
Surf Cond Disc 7480	4.00	6.62	26.48	Shop labor rate reduced from 108.50/hour to 98.50 per hour as normal for Cumberland Fire. We appreciate the opportunity to serve you.	
Rockwell HD Cast Brake Shoe w/ Lining KSMA403T4515CP	4.00	223.19	892.76	Environmental Fee	15.95
Brake Hdw Kit E3518	2.00	117.58	235.16		
HD Bal Brake Drum 66884	2.00	237.15	474.30		
Cut Off Wheel 01989	1.00	11.93	11.93		
Roloc Disc 01407	2.00	10.99	21.98		
HD Long Stroke Brake Chamber 36/36	2.00	289.94	579.88		

Ralco Equipment Company, Inc
 51 Ralco Way/PO Box 35
 Cumberland, Rhode Island 02864-0035
 Phone: 401-726-3095 Fax: 401-726-6950
We do the job once and we do it right!

9467
 Org. Est. # 016148
 RI Inspect Station 155C
 ralcotruck45@gmail.com

INVOICE

Print Date : 11/27/2017

Cumberland Fire Department - Chief Finlay
 3502 Mendon Road
 Cumberland, RI 02864
 Office 401-658-0544 --- Cellular 401-474-0314 Fin
 Cust ID : 934

2004 Pierce - Enforcer Fire Engine
 Cummins ISL, Disc Front, Drum rear
 Lic # : 1185 - RI Odometer In : 53,439
 Unit # : E4 Odometer Out :
 VIN # : 4P1CT02AX 4A003781

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
MA3636SB					
WASHER	4.00	2.31	9.24		
8FW58F					
LOCK NUT	4.00	3.87	15.48		
8SLN58C					
Frg Yoke Assy w/ Pin Kit	2.00	49.94	99.88		
R810019					
Half Jam Nut	2.00	2.62	5.24		
5856HF					
HD Brass 45 Deg Street Elbow	4.00	7.97	31.88		
38MP4538					
Teflon Tape	1.00	2.79	2.79		
06195					
Air Line Holder/Divider	5.00	9.11	45.55		
11549					
Shop Supplies			9.95		

[Technicians : Vecchio, JR, Theodore 20; Vecchio, Joseph 21]

Org. Estimate	\$ 5,181.10	Revisions	\$ 0.00	Current Estimate	\$ 5,181.10	Additional Cost	Revised Estimate	Labor:	1,945.38
								Parts:	3,219.77
								Sub:	5,165.15
								Tax:	0.00
								HazMat:	15.95
								Total:	\$5,181.10
								Bal Due:	\$5,181.10

[Payments -]

I hereby authorize the above repair work to be performed. I hereby grant you or your employees permission to operate the car or truck herein described on street, highways, etc for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. All sums shall become due and payable upon completion. All legal, attorney, and/or collection fees pursuant to this contract shall be paid to Ralco Equip Co by the undersigned

Signature.....

Date..... Time.....

Written By: Vecchio, JR, Theodore